

Port & Company[®] Tall 50/50 Cotton/Poly T-Shirts PC55T

PRODUCT MEASUREMENTS

	LT	XLT	2XLT	3XLT	4XLT
Chest	22	24	26	28	30
Length	33	34	35	36	37
Sleeve Length	20 3/4	21 3/4	22 3/4	23 3/4	24 3/4

CHEST LENGTH

Measured across the chest one inch below armhole when laid

flat.

Measured from center front neck to hem.

SLEEVE LENGTH

Start at center of neck and measure down shoulder, down

s leeve to hem.